

Photo 1 – South end of “as built “road between Blocks 3 and 4



Photo 2 – Filter fabric at culvert outlet

Photo 3 – Sediment at culvert inlet



Photo 4 – Moist cutbank

Photo 5 – Partially buried culvert inlet



Photo 6 – Rudimentary energy dissipator at culvert outlet

Photo 7 – Culvert inlet in shallow inside ditch



Photo 8 – Looking westerly at the Valhallas